

Oregon Department of Geology and Mineral Industries
Geological Map Series GMS-105

Erratum

In GMS-105, *Relative Earthquake Hazard Maps of the Salem East and Salem West Quadrangles*, on Plate 2 (Amplification Susceptibility Map), the Explanation defining Category 1 should read:

<1.2 amplification factor for peak rock accelerations
(i.e., symbol "<" rather than symbol ">").

Oregon Department of Geology and Mineral Industries
Geological Map Series GMS-105

Erratum

In GMS-105, *Relative Earthquake Hazard Maps of the Salem East and Salem West Quadrangles*, on Plate 2 (Amplification Susceptibility Map), the Explanation defining Category 1 should read:

<1.2 amplification factor for peak rock accelerations
(i.e., symbol "<" rather than symbol ">").