
Disclaimer: This product is for

informational purposes and may

PLATE 9

This map is an overview map and not intended to provide details at the community scale. The GIS data that are published with the Morrow County Multi-Hazard Risk Assessment can be used to inform regarding queries at the community scale.





Channel migration is a process by which a stream's course changes over time due to bank erosion and stream deposition. The channel migration zone is defined by the 30-year Erosion Hazard Area (EHA). Shown are the 30-year in Morrow County. Buildings within these areas are at greater risk to channel migration hazard than other areas.

Channel Migration Hazard Zone


30-Year Erosion

Data Sources:

Channel migration zone (30-year): DOGAMI (Appleby and others, 2021) Roads: Oregon Department of Transportation Signed Routes (2013) Place names: U.S. Geological Survey Geographic Names Information System (2015) City limits: Oregon Department of Transportation (2014) Basemap: Oregon Lidar Consortium (2014) Hydrography: U.S. Geological Survey National Hydrography Dataset (2017)

Projection: NAD 1983 UTM Zone 10N Software: Esri® ArcMap 10, Adobe® Illustrator CC Cartography by:Matt C. Williams, 2023





Irrigon