
STATE OF OREGON DEPARTMENT OF GEOLOGY AND MINERAL INDUSTRIES DONALD A. HULL, STATE GEOLOGIST



Open File Report O-95-59 Tsunami Hazard Map of the Gold Beach Quadrangle, Curry County, Oregon

Tsunami inundation boundaryupper limit of area expected to be covered by flood water from a tsunami caused by a magnitude 8.8 undersea earthquake

See accompanying text for use of this map, mapping methodology, and acknowledgments.

Mapping by:

George R. Priest, Oregon Department of Geology and Mineral Industries, October-November, 1995.